

Greenbelt Project 983

Achieve a 50% Reduction In Forklift Truck Related Incidents (Damage to Plates)

Roger Rustom MIIRSM



Kodak





Define

Project 983 Summary

Target: - **50%** Reduction in FLT Incidents (Damage to plates)

Problem: - **168** recorded FLT incidents in the last 12 months

Resulting in: **9570** m2 scrapped plates

£15130 scrapped plates

£20000** other damage

** Figure is an estimate as not all incidents recorded

Scope: - Unwrapped plates between the end of the conveyor and the wrappers

Business Case: - To have a safe working environment and to minimise loss due to damage

Goal: - **50%** reduction – equates to **84** FLT incidents

Metrics: - Baseline **13.81** incidents/month

- Target **7** incidents/month

Team: - T Cook, C Wake, A Garnett, H Gillet, S Leather, S Harding, D Lawrence, M Ramsden

Background

168 Forklift Truck (FLT) related incidents have been reported between Sept 06 – Sept 07. This figure is a minimum as not all incidents are reported or easily identifiable as FLT type damage.

The HSE believe that only around **46%** of all incidents are actually reported. (www.hse.gov.uk)


This means there have potentially been between **168** and approximately **365** incidents and therefore opportunities to cause injury or damage.

We need to greatly reduce the number of incidents in order to reduce the likelihood of injury to persons and damage to product.


The Pareto chart on the following page shows all recorded incidents across the Leeds Manufacturing site.

All Incidents Pareto Chart

Pareto Chart of Incident Type




SIPOC Diagram



Process Steps:



Stakeholder Plan



Voice Of The Customer

What

- Metal
- Consumables
- Waste

Who

- FLT Drivers
- Factory Areas – e.g. CTL
- Finance Dept
- Team Leaders
- Operations Manager


Why

- Damage
- Plates
- Right First Time
- Less Re-Work
- Downtime / Repairs

Information Providers


- EHS Database
- Quality Database
- Quality Department
- PPIC & SAP etc
- FLT Drivers

Critical To Quality Diagram






All Incidents Pareto Chart




Examples of damage caused by Forklift Trucks



Examples of damage caused by Forklift Trucks




Incident I Chart – showing mean incident rate/month




Incident Probability Plot – checking for normal data


Normal - 95% CI




I Chart All Box Sizes excluding outliers




Site Pareto Chart




Pareto Chart for Warehouse Areas



Pareto Chart for Wrappers



Cut to Length Pareto Chart



Count
Percent
Cum %

CTL Jagenburg

CTL Baler Area

CTL Georg

27

12

12

52.9

23.5

23.5

52.9

76.5

100.0

Measure Summary

- The initial scope of the project was to look at all incidents relating to FLT's, however it was determined that it needed to be more focussed on FLT damage to plates as this has the most direct affect on the customer
- The main area of focus for this project was from when the plates are taken off the CTL conveyor and until they reach the wrappers

Therefore the following were discounted from the scope of the project:

- FLT damage to anything other than plates
- Damage occurring within the coil line areas – not enough reported incidents
- Damage occurring in the warehouse area – most damage to plates occurs when they are unwrapped

Analyse



Analyse Introduction


As part of the project drivers were involved in discussions as to the most likely causes of damage to plates caused by FLT's and the following theories were put forward:

1. The more Work In Progress (WIP) there is the more likely there is to be damage to plates?
2. Are there particular plate sizes that are more likely to be damaged? (Box sizes were used to group plate sizes together)
3. Damage is more likely to occur during night shifts
4. Are there differences between shifts?
5. What effect do the FLT drivers have?

Work In Progress vs. Incidents – checking for relationship

Fitted Line Plot


$$\text{Incidents} = 13.89 - 0.040 \text{ WIP (in Million m2)}_1$$



S	4.57357
R-Sq	0.0%
R-Sq(adj)	0.0%

Pareto Chart of Normalised Data for Incidents / Million Plates



Pareto Chart of Box Size



Box Size	Size 7	Size 4	Size 3	Size 2	Size 6	Size 5
Count	203	98	86	57	37	33
Percent	39.5	19.1	16.7	11.1	7.2	6.4
Cum %	39.5	58.6	75.3	86.4	93.6	100.0




Determining Differences Between Night & Day Shifts




A comparison of shifts was carried out to determine if there was a difference between day and night shifts using both boxplots and ANOVA tests and it was determined that there was NO statistical difference

Opportunities for Forklift Truck damage to occur




Spaghetti Diagram of Plate Movements



FLT Damage Cause and Effect Diagram

Cause and Effect Diagram



Analyse Summary

From the information and statistical analysis gathered during the course of this project several points have come to light:

1. The amount of WIP on the shop floor does not affect the number of incidents recorded. More WIP does not equal more damage
2. The area where most damage occurs is between the end of the conveyor and the wrappers
3. Once the plates are wrapped there are very few FLT related incidents occurring
4. There was no significant difference between shifts
5. No statistical difference between day and night shifts
6. Size 7 plates are the most likely to be damaged



Fork Tip Protectors

A new product designed to reduce impact damage caused by Fork tips

- Constructed of Polyurethane
- Fixed to Fork Tips by plastic weld type gluing process
- Initial trial to begin with fitment to one Electra FLT and the Non-Standards FLT on Tuesday 26th August
- Approximate Cost to fit to remaining 8 Reach FLT's = <£2200 = £275/FLT



Fork Tip Protector Installation Process



Fork Tip Protector Kit & Video

A Short
Video Clip
(Separate
Video File)



Improve Summary


- Confirm effectiveness of Fork Tip Protectors – monitor safety and quality incident databases - no reported FLT damage to plates in Electra area caused by FLT's since 26th August – 11 weeks (to 10/11/08)
- Fit remaining suitable FLT's with fork tip protectors – 8 reach trucks – date to be agreed

Control




Control & Sustain


- Monitor incident rate
- Design site layouts with ideal routes
- Create checklist for operators to improve operating standards e.g. check load before lifting
- Ensure FLT operation remains a focus by including in Safetrack topics regularly, toolbox talks on expected standards of operation
- Produce guidance for non-FLT personnel to help detect and deal with poor operation
- Ensure reporting of FLT damage is completed with as much information as possible
- Post at regular intervals incident statistics and information



Incidents Rate Before and After Project Started




Control & Sustain continued



Control & Sustain continued


Costs & Savings



Completed Solution

Barrier Alteration – Quick Win

- The position of this barrier means that it gets clipped on a regular basis when moving pallets by the end of the conveyor
- Angle the barrier more to improve the access to the conveyor area and to modify the gate accordingly (both low cost modifications). This reduces the likelihood of damage to plates due to better access to the end of the conveyor



Further Recommendations


Outside the scope of this project but will have benefits

1. Determine future strategy for Forklift Trucks and adjust as appropriate – [Action RR / PW / DD](#)
2. Retrain all remaining drivers as per RTITB recommendations – [Action RR / PW](#)
3. Investigate key fob system to encourage ownership of FLT – [Action RR / PW](#)
4. Continue to work with fork tip protector supplier to enhance and improve design – [Action RR](#)
5. Investigate the fitting of protective corners to Size 7 pallets at CTL to reduce likelihood of damage – [Action NC / SA / DD](#)
6. Conveyor Alterations (see next slide) – [Action JL](#)

Further Suggested Solutions

Conveyor Alterations

- Remove the last section of conveyor to allow FLT's to unload pallets from the end. (this would reduce the handling of pallets as the drivers would be able pick the pallet up the way it needs to be stored in the racks)
- Remove a section of the plinth to continue to allow FLT's to unload from the side as well (relatively low cost modifications)





Questions ?



Kodak

